

Internal
S009 0004



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program August 9, 2010

Reviewed: PTTB

Mine Name: Daggett County Clay Pit	Permit Number: S/009/0004
Operator Name: Daggett County	Inspection Date: June 16, 2010
Inspector(s): L Heppler	Time: 9:00 am
Other Participants: none	Mine Status: Ina

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection: Routine annual inspection. This site was inspected as a small mine site on 07/29/2009

Inspection Summary: Every effort should be made to salvage topsoil from the site prior to mining. There is no topsoil storage at the largest disturbed site. Multiple disturbances were noted. The current working face and pit area has topsoil that has been stockpiled for future reclamation. Old engine has been removed from the middle pit area. Photos were taken to document site conditions.

Conclusions and Recommendations: There is no bond posted for these sites. Operator should either bond for the total disturbance on the ground or reclaim the areas that are mined out and bond for one working face at a time. It is the recommendation of the Division to interm seed (Crested Wheatgrass) the working faces, top soil stockpile and adjacent areas to help eliminate the opportunity for weeds to dominate the site and spread to other adjacent areas. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature L. Heppler


LAH:vs

cc: James Olson

SITLA - Jblake@utah.gov

O:\M009-Daggett\S0090004-DaggettCountyClayPit\inspections\Insp-06162010.doc







Middle Pit



Middle Pit



Working pit – Note Topsoil stockpile



Working pit – Note Topsoil stockpile